

### HUD-REAC TRAINING

Resource Book

HUD ASSIST

powered by

CONSTRUCTIVE FORENSICS

Nathi Markan
Director of the HUD Assist Division
kmarkan@c4n6.com





### NSPIRE - The New REAC Inspection

- NSPIRE = National Standards for the Physical Inspection of Real Estate
- The "2-year" Demonstration began in late 2019
  - The current extension of the Demo was through June 30, 2023 for PHAs
  - The current extension of the Demo is through September 30, 2023 for MF and HCV properties
- Approximately 4,500 properties from a pool of volunteers were part of the NSPIRE Demo
  - HUD only conducted 2,335 NSPIRE inspections on MF and PHA they spent most of their time in HCV units where they have conducted over 9,200 NSPIRE-V inspections.
- https://www.hud.gov/program offices/public indian housing/reac/nspire
- The Demo was conducted to test a protocol that would improve objectivity, defensibility and accuracy for a more reliable assessment of housing conditions
- The scope of the inspection, procedural guidelines and many individual deficiencies have been
  modified to remove <u>subjectivity</u>, <u>ambiguity</u>, and to <u>emphasize</u> those areas that present the
  highest risk of harm for those living in HUD housing.
- This program will completely overhaul the current 25-year old UPCS inspection protocol (aka REAC Inspections)
  - New software
  - New Protocol
  - New scoring model

Constructive Forensics





### **NSPIRE Demonstration Details**

- > The primary difference between NSPIRE and UPCS is that NSPIRE gives <u>precedence to the Units</u> over the physical condition of other areas of the property.
- NSPIRE aligns multiple HUD programs (Loans, PHA, HCV, etc) to a single set of Standards
- The inspections will be flexible based on the needs of the program
  - o Properties subject to scored UPCS inspections will get a scored NSPIRE inspection
  - o Tenant-based programs (HCV) will have a pass/fail result like they do for HQS inspections
- Federal programs may have unique protocols for how the standards are applied HUD will provide this
  information in future notices
- > To improve objectivity, accuracy and consistency many things were tested during the demonstration:
  - Standards
  - o Protocols
  - Processes
  - A primary goal was to have different inspectors inspect the same property and arrive at similar outcomes
  - Assess whether deficiencies needed to be added to or removed from the current Standards

Constructive Forensics



### Housing Choice Voucher (HCV) Specific Details


From the NSPIRE Get Ready Sessions:


- ➤ NSPIRE for HCV inspections are expected to begin on 10/1/23 and will replace HQS
  - They will forevermore be called NSPIRE-V inspections
- ➤ The NSPIRE inspection will be conducted on an <u>updated</u> HUD-52580 \*
- The current form expires 04/30/2026
- ➤ Inspectors can use the paper HUD-52580 form or software on a tablet \*
- Housing Authorities can elect to start NSPIRE on 10/1/2024 (keeping HQS for another year) \*
  - You MUST report this choice to HUD's field office (not DC) \*

\*HCV/PBV/CPD programs:


"HUD will issue additional Departmental notices before 10/1/2023"\*


Constructive Forensics






Constructive Forensics










Low	(fka Advisory) Deficiencies	
✓ Function & Operability and Conc	dition & Appearance <u>used to be</u> considered Low Deficiencies	
✓ As of 5/11/23 per the NSPIRE Fir Safety	nal Rules, HUD now lists Low Deficiencies as a Health and	
✓ 60 days to repair per the Final ar	nd Effective published rule on 5/11/23	
✓ Defined as: "Deficiencies critical safety risk to the resident."	to habitability but not presenting a substantive health or	
✓ ONLY the following Low Deficien	cies will be considered a "PASS" for a NSPIRE-V inspection	
✓ These are <u>ALL</u> of the Low Deficie	encies in the NSPIRE Standards	
14	Constructive Forens	sics

Low Deficiencies – requires repair in 60 days	Location Recorded
Only 1 bathtub or shower is present and it is inoperable or does not drain	Inside
A bathtub/shower is inoperable or does not drain and at least 1 bathtub/shower is present elsewhere that is operational	Inside
Bathtub/shower component is damaged, inoperable, or missing that <u>mav</u> limit the resident's ability to maintain personal hygiene	Inside
Bathtub/shower component is damaged, inoperable, or missing and it does <u>not</u> limit the resident's ability to maintain personal hygiene	Unit
50% or more storage components are damaged, inoperable or missing	Inside
Cooking range, cooktop, or oven does not ignite or produce heat	Inside
Entry door component is damaged, inoperable, or missing and it does not limit the door's ability to provide privacy/protection from weather/infestation	Unit/Inside
A passage door component is damaged, inoperable, or missing and the door is not functionally adequate	Unit/Inside
A passage door that is not intended to permit access between rooms has a damaged, inoperable, or missing component	Unit
Exterior dryer vent cover, cap, or a component thereof is missing	Outside
Handrail not installed where required (HUD has error where Deficiency is not categorized)	Unit*/Inside/Outside
Air conditioning system or device is not operational	Inside
Litter is accumulated in an undesignated area	Outside
Plumbing Leak	Outside
Fluid is leaking from sprinkler assembly	Outside
Presence of mold-like substance at moderate levels is observed visually	Inside
Elevated moisture level	Inside

Sink or sink component is damaged or missing and the sink is NOT functionally adequate Sink - Water is directed outside of the basin Sink or sink component is damaged or missing and the sink IS functionally adequate Water runoff is unable to flow through the site drainage system Torsion is present Toilet component is damaged, inoperable, or missing and it does not limit the resident's ability to discharge human waste No hot water Window will not open or stay open (as long as there are other egressable windows in that room) Window cannot be secured	
Sink – Water is directed outside of the basin Sink or sink component is damaged or missing and the sink IS functionally adequate Water runoff is unable to flow through the site drainage system Frosion is present Tollet component is damaged, inoperable, or missing and it does not limit the resident's ability to discharge human waste No hot water Window will not open or stay open (as long as there are other egressable windows in that room)	
Sink or sink component is damaged or missing and the sink IS functionally adequate  Water runoff is unable to flow through the site drainage system  Erosion is present  Toilet component is damaged, inoperable, or missing and it does not limit the resident's ability to discharge human waste  No hot water  Window will not open or stay open (as long as there are other egressable windows in that room)	Inside
Water runoff is unable to flow through the site drainage system Frosion is present Frosion is present Frosion is gressent Fros	Inside/Unit
Frosion is present  Toilet component is damaged, inoperable, or missing and it does not limit the resident's ability to discharge human waste  No hot water  Window will not open or stay open (as long as there are other egressable windows in that room)	Inside/Unit
Toilet component is damaged, inoperable, or missing and it does not limit the resident's ability to discharge human waste  No hot water  Window will not open or stay open (as long as there are other egressable windows in that room)	Outside
No hot water  Mindow will not open or stay open (as long as there are other egressable windows in that room)	Outside
Window will not open or stay open (as long as there are other egressable windows in that room)	Unit/Inside
	Inside
Window cannot be secured	Inside
	Inside





## Some of the most unreasonable/outrageous 24-hour required repairs (NOT a complete list) 1. Structural system exhibits signs of serious failure 2. Foundation appears to be in imminent danger of collapse or failure. 3. Fire-labeled doors – whether it's a hole of any size or the seal/gasket is missing/damaged or self-closing hardware does not work 4. Bldgs built prior to 1978 and there is >2 sq ft peeling paint per room OR >10% per component or >20 sq ft outside 5. Paint or foreign material on sprinkler head assembly. (More than 75% of the assembly OR bulb) 6. Extensive cockroach/bedbug/mouse/rat infestation

### 2023 Repair Reporting Update

- HUD realizes that the 24-hour and 30-day repair requirements are not practical nor sustainable and state
  they will accept a time-line communication of the repair.
  - ✓ For LT and Severe Deficiencies, "Corrected" will mean that the PHA/POA has
    - 1. Completed all the repairs, or
    - 2. Has controlled/blocked access to the hazard (temporarily)
    - 3. Temporarily relocate the resident while repairs are made
      - "Residents should be temporarily relocated until mold and moisture conditions are controlled" (Page 15 of the Admin Notice)
- Since this will all be reported online, the deficiency will remain "open" until the repair is complete.
- You will also be able to condense your reporting, for instance, if you have 20 smoke alarms recorded during your inspection, you could upload that "20 smoke alarms repaired/replace on x date" instead of reporting on each individual one.
- Per the Final Rule, <u>ONLY</u> LT and Severe H&S will have the repair reporting requirement

   not Moderate H&S or Low deficiencies

### 20

# 3 Inspectable Areas ❖ UNIT • Refers to the interior components of an individual unit ❖ Inside • Refers to the common areas and building systems generally found in the building interior and are not inside a unit ❖ Outside • Refers to the Building Site, Building Exterior components and any Building Systems located outside a building or unit • This allows inspectors to cite deficiencies based on where they are standing and will reportedly remove subjectivity or ambiguity about a deficiency's location • Location may change the impact on resident health & safety – this will be clearly described in the rationales • For Example: An inoperable toilet in a unit may have a different rationale and health & safety classification than one in a common area.

### 2023 Repair Reporting Update (cont.)

The 24-hour correction timeframe commences immediately upon notification by the inspector and does

### NOT PAUSE FOR NON-WORKING HOURS, INCLUDING WEEKENDS!

- ❖ If you can't permanently repair something within 24 hours, you must provide HUD with a timeframe and get HUD's approval in writing. This should be conducted via email to the field office representative with a courtesy copy to <u>NSPIRERegulations@hud.gov</u> until HUD gets the NSPIRE System fully operational.
- All evidence of repair must be submitted within 48 hours after the 24-hour deadline (allowing 72 hours for the full process) Evidence includes:
  - Work orders
  - Invoices
  - Photos (as long as it matches the deficiency photo)

21

### Scoring – Differences between UPCS and NSPIRE

UPCS	NSPIRE
Complex system of weightings, multipliers, and limits	Simplified four-step scoring system
Unsafe properties could still receive a passing score for a variety of reasons, including mechanisms of "capped" item and area weights	Unsafe properties will not receive a passing score due to focus on Health & Safety and Unit-based defects
Item and area weights could sometimes cause less important defects to disproportionately factor into inspection scoring	Defect Impact Weights Table makes clear the hierarchy of defect importance on Inspection Score

Defect Severity Category	In	Inspectable Area*		
	Outside	Inside	Unit	
Life-Threatening (LT) (most severe)	49.6	54.5	60.0	
Severe	12.2	13.4	14.8	
Moderate	4.5	5.0	5.5	
Low	2.0	2.2	2.4	
*Defect impact weights are rounded to the tenths place				

Under the draft NSPIRE Scoring Model, the steps to score an inspection are as follows:


- 1. Count defects of each type. Multiply counts by values in Defect Impact Weights table (shown in the previous slide). Sum all results. Calculation yields **total defect points.**
- 2. Size-adjust total defect points.
  - Divide total defect points by number of units inspected to adjust for property size
- 3. Subtract size-adjusted defect points from 100 to calculate **0-100 score.**
- 4. Sum **defect points in units category,** then divide by total number of units sampled. If less than 30 the property passes the "Unit Standard of Performance" test.




	Total N	umber of	Defic	ciencies				
Defect Severity Category	Outside	Inside		Unit	Property Z i	s 22 Building	gand 97 Un	iits
					21 U	nits were ins	pected	
Life-Threatening	0	0		5	RFA	C/UPCS SCO	RE: 70	
Severe	0	0		8	Defect Severity		table A	rea*
Moderate	0	0		56	Category	Outside	Inside	Unit
Low	0	0		42	Life-Threatening (LT)	49.6	54.5	60.0
Defect Severity Category	O	utside In	side	Unit	Severe	12.2	13.4	14.8
Life-Threatening		0	0	300	Moderate	4.5	5.0	5.5
Severe				118.4				
Moderate		0	0	308	Low	2.0	2.2	2.4
Low				100.8		LIVE	411-	
Total by Inspectable Area		0	0	827.2				
Size-Adjusted for 21 Units	(Divide)	0	0	39.39 🖪				
Final score (subtract from	100)			6)61				

	Call-for-Aid System	Blocked or pull cord is higher than 6 inches from the floor	Fire Extinguisher	Service tag is missing, illegible, or expired	
	Call-for-Aid System	System does not function properly	Fire Extinguisher	Damaged or missing	
	Carbon Monoxide Alarm	Missing, not installed, or not installed in a proper location	Flammable and Combustible Item	Item is on or within 3 feet of an appliance that provides heat for thermal comfort or a fuel-burning water heater or improperly stored chemicals	100 100
	Carbon Monoxide Alarm	Obstructed	Guardrail	Missing or not installed (more than 30 in above floor/grade below)	
	Carbon Monoxide Alarm	No audio or visual alarm when tested	Guardrail	Not functionally adequate - missing/damaged components, less than 30 in high, not securely attached	UNITS
	Chimney	Incomplete or damaged	HVAC	The inspection date is on or between October 1 and March 31 and the permanently installed heating source is not working or the permanently installed heating source is working and the interior temperature is below 64 degrees Fahrenheit.	43 – LT
	Clothes Dryer Exhaust Ventilation	Electric dryer transition duct is detached or missing	HVAC	Unvented space heater that burns gas, oil, or kerosene is present	33 – Severe
	Clothes Dryer Exhaust Ventilation	Gas dryer transition duct is detached or missing	HVAC	Combustion chamber cover or gas shutoff valve is missing from a combustion- fueled heating appliance	79 – Modera
	Clothes Dryer Exhaust Ventilation	Electric dryer exhaust ventilation system has restricted airflow	HVAC	Fuel burning heating system or device exhaust vent is misaligned, blocked, disconnected, improperly connected, damaged, or missing.	
	Clothes Dryer Exhaust Ventilation	Dryer transition duct is constructed of unsuitable material	Leak - Gas or Oil	Natural gas, propane, or oil leak	
	Clothes Dryer Exhaust Ventilation	Gas dryer exhaust ventilation system has restricted airflow	Mold-Like Substance	Presence of mold-like substance at extremely high levels is observed visually. (over 9 sq ft)	
	Door - Entry	Entry door is missing	Smoke Alarm	Smoke alarm is not installed where required. (Inside bedroom, outside bedroom and on each level)	
	Door - Fire Labeled	Fire labeled door is missing	Smoke Alarm	Obstructed	
	Egress	Obstructed means of egress	Smoke Alarm	Does not produce audio or visual alarm when tested	
	Egress	Sleeping room is located on the 3rd floor or below and has an obstructed rescue opening	Sprinkler Assembly	Sprinkler head assembly is encased or obstructed by an item, object, or encasement within 18 inches of the sprinkler head.	
	Egress	Fire escape access is obstructed	Sprinkler Assembly	Component is damaged, inoperable, or missing and it is detrimental to performance.	
	Electrical - Conductor, Outlet and Switch	Outlet or switch is damaged	Sprinkler Assembly	Sprinkler assembly has evidence of corrosion.	Boll.
	Electrical - Conductor, Outlet and Switch	Exposed electrical conductor	Sprinkler Assembly	Sprinkler assembly has evidence of foreign material that is detrimental to performance. (More than 75% of the sprinkler assembly or glass bulb)	
	Electrical - Conductor, Outlet and Switch	Water is currently in contact with an electrical conductor	Structural System	Exhibits signs of serious failure	
	Electrical - Service Panel	The overcurrent protection device is damaged	Toilet	Only 1 toilet was installed, and it is missing.	
7	Fire Extinguisher	Gauge reads over or undercharged	Water Heater	Chimney or flue piping is blocked, misaligned, or missing.	
			Water Heater	Gas shutoff valve is damaged, missing or not installed	


### **Shortcut Method of Scoring** 1. Use the NSPIRE Sample Chart (Slide 44) to determine how many units will be inspected at 2. Divide EACH of the values from the Impact Table (slide 24) by how many units will be inspected. Inspectable Area **Defect Severity Category Actual Point Loss** Outside Inside Unit Life-Threatening (LT) (most severe) 1.98 2.18 2.40 Severe 0.49 0.54 0.59 Moderate 0.18 0.20 0.22 0.08 Low 0.09 0.10 Example: If you have 100 units at your property, 25 units will be inspected. Values in table above reflect the ACTUAL point loss for EACH recorded deficiency based on 25 units inspected









Deficiency	Severity	Size-Adjusted Point Loss
THE INSPECTION DATE IS ON OR BETWEEN OCT 1 AND MARCH 31 AND THE PERMANENTLY INSTALLED HEATING SOURCE IS NOT WORKING OR THE PERMANENTLY INSTALLED HEATING SOURCE IS WORKING AND THE INTERIOR TEMPERATURE IS BELOW 64 DEGREES FAHRENHEIT	it •	2.4
GFCI OUTLET OR GFCI BREAKER IS NOT VISIBLY DAMAGED AND THE TEST OR RESS BUTTON IS NOT WAS IN	SEVERE	0.59
OUTLET DOES NOT HAVE VISIBLE DAMAGE AND TESTING INDICATENT S NOT THE SELECT OF THE SEL	SEVERE	0.59
NO HOT WATER	SEVERE	0.59
COOKING RANGE, COOKTOP, OR OVEN DOES NOT IGNIZE THE RODUCE HEAT	SEVERE	0.59
A PERMANENTLY INSTALLED LIGHT FIX UNE SINOPERABLE	MODERATE	0.22
KITCHEN EXHAUST SYSTEM DOES NOT RESPOND TO THE CONTROL SWITCH	MODERATE	0.22
BATHROOM DOES NOT HAVE PROPER VENTILATION OR DEHUMIDIFICATION	MODERATE	0.22
REFRIGERATOR IS INOPERABLE SUCH THAT IT MAY BE UNABLE TO SAFFELY AND ADEQUATELY STORE FOOD	MODERATE	0.22
		The second second







### Scoring: The Good...the Bad...and the Weird

"HUD understands that it may take properties' ownership and management some time to comply with new affirmative requirements, hence, **HUD will <u>NOT</u>** score new affirmative requirements, which are defined as those standards that were expressly <u>NOT</u> in the UPCS <u>or in any way covered</u> by those standards, in at least the first 12 months of NSPIRE inspections."

- HUD lists only 5 Affirmative Requirements that will not be scored (out of 14):
  - 1. GFCI (not within 6 feet of water source)
  - 2. Guardrail (All defects...although only Deficiency 1 is an Affirmative Standard)
  - 3. HVAC (Deficiencies 1, 2, 7 ...they forgot to add Deficiency 9)
  - 4. Interior Lighting (Def #3 "At least 1 permanent light fixture is not present in the kitchen and bathroom")
- 5. At least 2 working outlets or 1 working outlet and 1 permanently installed light fixture in each room.



- What about the approx. 60 brand new NSPIRE deficiencies that were never seen in UPCS?!
- HUD tacks on <u>ALL</u> deficiencies under Fire Doors also will not be scored since many of the deficiencies are new...even though it is NOT listed as an affirmative requirement
- New requirements that are not scored will be flagged on the inspection report with a caret (^) symbol.
- For at least the initial year, HUD will provide a "potential score" if the new requirements were scored and the
  "official score" on the inspection report.

36

### MAJOR SCORING ANNOUCEMENT (from June Standards Final Rule)

\*\*\* The Infestation, Mold-Like Substance, and Potential Lead-Based Paint Hazards — Visual Assessment Standards will include Deficiencies that are scored at the Life-Threatening level point deduction... despite being defined in the Severe H&S category.\*\*\*

### Reasoning

- These Severe Health and Safety Deficiencies do not present risks consistent with the Life-Threatening definition, but they do present chronic health risks that are distinct from the other Severe Health and Safety Deficiencies.
- 2. This chronic health risk category includes deficiencies that, if evident in the home or on the property, present a high risk of causing or exacerbating a chronic and severe health condition; severe health conditions include permanent disability or serious illness. This includes cases in which the harm has a likelihood of accruing irrevocably in under 24 hours and may also include risks due to longer term exposure. This category does not define an additional risk ranking or correction timeframe; it is a sub-category to be used for scoring.

### Random Extra Takeaways from Final Scoring Notice

- Calculated scores will be rounded to the nearest whole number with one exception: For properties that score between 59.5 and 60, the score will be rounded DOWN to 59.
- Per page 20, "Inspection scores are considered when determining whether a potential or existing HUD Multifamily business stakeholder may expand its involvement in HUD housing."
- 3. On pages 5 and 14, HUD insists that 1 unit cannot fail an inspection.
  - I fully agree that many people misunderstood that the "30 points or more in Units" meant 30 SIZE-ADJUSTED points (you had to divide the defect points in Units by how many Units were inspected!
  - That being said, if each Life-Threatening defect equals 2 points, then 1 or 2 "bad" units with a total of 15 LT defects between them would, in essence, fail the inspection.
- 4. On page 7, the Notice states, "Some UPCS standards, such as overgrown vegetation, erosion, and graffiti are no longer standards." There are a few things wrong with this sentence:
  - Overgrown Vegetation and Erosion were never Standards.
  - Overgrown Vegetation was <u>never</u> even a deficiency under NSPIRE (except if blocking a sidewalk)
  - Erosion is still a deficiency located under Site Drainage Standard.

37

### 2023 Scoring Update

HUD is strongly considering allowing properties to apply for funding to satisfy the new requirements as well as potentially tying NSPIRE results to capital funding.

- ✓ For PHAs Google PIH 2023-10 \$250K per Federal Fiscal Year
  - Includes Carbon Monoxide and Smoke Alarms/Detectors
  - And so much more!

There are a lot of new NSPIRE deficiencies that could result in high capital expenditures

✓ For instance, if your property has 2-prong outlets and you want to run a ground wire in to upgrade the 2-prongs to a 3-prong, that could get very expensive.

39

### Deficiencies that will NOT be scored "for the foreseeable future" (per Final Scoring Rule) ALL 3 INSPECTABLE AREAS 1. Carbon Monoxide Alarms – all defects – indicated on report by a + sign 2. Smoke Alarms – all defects – indicated on the report by a \* sign 3. Call-For-Aid – Deficiency #1 (System is blocked or pull cord is higher than 6 inches from the floor) a. Handrail is missing b. Handrail is not installed where required

### Deficiencies that will NOT be scored UNTIL OCTOBER 1, 2024 (per Final Scoring Rule)


For BOTH PHA and Multifamily Programs – all of the following will be indicated on the report by a caret ^ symbol

- 1. Fire Doors
  - a. All defects
  - b. All locations
- 2. Electrical GFCI
  - a. Deficiency 3 An unprotected outlet is present within six feet of a water source
- 3. Guardrail a. All defects
  - b. All locations
- - a. Between Oct 1 and March 31 heater works but interior temp is 64 to 67.9°F All locations
     b. Between Oct 1 and March 31 heater works or doesn't work temp inside below 64°F All locations
- c. Between April 1 and Sept 30 heater is damaged, inoperable, missing or not installed All locations
- - a. At least 1 permanently installed light fixture is not present in the kitchen and bathroom All locations
- a. At least 2 working outlets are not present within each habitable room OR 1 working outlet and 1 permanently installed light fixture is not present within each habitable room.

		A-B-C's	
90a*			
	a	No Health and Safeties at all	
	b	Regular H&S – no Exigent H&S	
	С	Exigent H&S were recorded	
	*	Only refers to Smoke Alarms/Detectors	
	CARBON MONO	XIDE SYMBOL = +	
- 10	Deficiencies that	t are not scored the first year = ^ (caret symbol)	
43			

Minimum Unit San	nple Size Reference Ch	art		Units in	NSPIRE	Units in	NSPIRE
Units on the Property	Minimum Unit Sample Size	Units on the Property	Minimur Sample	Property	Sample	Property	Sample
1 roperty	1	26 - 29	14	1	1	28-30	16
2	2	30 - 34	15	2	2	31-35	17
3	3	35 - 40	16	3	3	36-39	18
4	4	41 - 47	17				
5 - 6	5	48 - 56	18	4	4	40-45	19
7	6	57 - 67	19	5	5	46-51	20
8 - 9 10 - 11	7	68 - 81 82 - 101	20	6	6	52-59	21
12 - 13	9	102 - 130	22	7	6	60-67	22
14 - 16	10	131 - 175	23	8	7	68-78	23
17 - 18	11	176 - 257	24		-		
19 - 21	12	258 - 449	25	9	8	79-92	24
22 - 25	13	450 - 1461	26	10	8	93-110	25
1462 - 9999	27			11-12	9	111-120	26
UPCS		NCDIDE		13-14	10	121-166	27
UFCS		NSPIRE	the Older	15-16	11	167-214	28
				17-18	12	215-295	29
NEW	SAMPLE S	IZE CHAR	RT.	19-21	13	296-455	30
				22-24	14	456-920	31
44			4-74	25-27	15	921+	32

# NSPIRE Deficiency Rationales ♣ All deficiencies must tie back to a rationale ♣ Rationales are clear and concise explanations of the potential risk a defect presents ♣ 2 Types of Rationales 1. Direct Rationale If the deficiency were no longer present, the risk would be resolved 2. Indirect Rationale If the deficiency were no longer present, and other contributory factors remained, the risk would be substantially reduced or mitigated, but would remain present The "other contributory factors" include Environmental or structural variables and exposure to vulnerable populations



	► Breakdown  ■ There are 63 NSPIRE Standards poste	ded 1 (Version 2.2 had 62 Standards)  nsolidated deficiencies  ning many Standards		
		UPCS TOTAL	NSPIRE TOTAL	
	Total Deficiencies	140	200 (conservative – accounts for same defect in multiple areas)	
	UPCS Exigent H&S (24-hour repair) VS NSPIRE LT and Severe (24-hour repair)	16	76 – Unit 103 – Inside 38 - Outside	
. 611	Regular UPCS H&S (no repair req) VS NSPIRE Moderate H&S (30-day repair)	12	79 – Unit 82 – Inside 43 - Outside	
47	NON-H&S UPCS VS NSPIRE Low H&S (60-day repair)	112	8 – Unit 18 – Inside 7 - Outside	

Version Inspectable Item		Deficiency	Low	Moderate	Severe	LT
V3.0	Bathtub and Shower	Only 1 bathtub or shower is present and it is inoperable or does not drain.			х	
V3.0	Bathtub and Shower	A bathtub or shower is inoperable or does not drain and at least 1 bathtub or shower is present elsewhere that is operational.		х		
V3.0	Bathtub and Shower	Bathtub component or shower component is damaged, inoperable, or missing such that it may limit the resident's ability to maintain personal hygiene.		х		
V3.0	Bathtub and Shower	Bathtub component or shower component is damaged, inoperable, or missing and it does not limit the resident's ability to maintain personal hygiene.	х			
V3.0	Bathtub and Shower	Bathtub or shower cannot be used in private		Х		
V3.0	Cabinet and Storage	Food storage space is not present		Х		
V3.0	Cabinet and Storage	50% or more storage component is damaged, inoperable, or missing		х		
V3.0	Call-For-Aid System	System is blocked, or pull cord is higher than 6 inches off the floor. *Not Scored				х
V3.0	Call-For-Aid System	System does not emit sound, light, send a signal to the annunciator, annunciator does not indicate the correct corresponding room, cord is missing or tied up such that it cannot be engaged.				х
V3.0	Carbon Monoxide Alarm	Carbon monoxide alarm is missing, not installed, or not installed in a proper location. *Not scored				х



### Current UPCS Deficiencies that are NOT in NSPIRE's Standards...(yet)

- 1. Non-Security Fence Deficiencies
- 2. Overgrown/Penetrating vegetation unless it forces you off a walkway
- 3. Playground Deficiencies
- 4. Mailbox Deficiencies
- 5. Swimming Pool Deficiencies
- 6. Spalling/Cracking in Parking Lots and Walkways
- 7. Generator Run Up Records
- 8. Litter/Garbage/Debris in Units
- 9. Hazards/Other category discussing adding this back in
- 10. Building built AFTER 1978 no peeling paint deficiencies Inside or Units must be over 10 square feet on the Outside to be recorded for properties built AFTER 1978
- 11. Inside and Unit wall trim (baseboard) damage
- 12. Exterior caulking damaged/missing
- 13. Outlet/Switch cover plates cracked with no exposed conductors
- 14. Flooring (hard floor or carpet) stains or peeling paint
- 15. Surface rust/corrosion on water heaters
- 16. Graffiti
- 17. Dual-pane windows with condensation between the panes (aka blown seal)
- 18. Dishwashers/Garbage Disposals unless leaking or exposing wires
- 19. Screen/Storm/Security Doors

Constructive Forensic

### Administrative Procedures Final Rule (cont.) Yellow = Different than UPCS

Inspectors will NOT inspect or cite as deficient:

- 1. Areas of the property that are not considered housing or part of the housing project (commercial space, sidewalks, fencing, roads and parking lots not owned or maintained by the property).
- Peeling paint in areas a child under age 6 would not frequent (e.g., locked utility closet)

  If you are exempt (elderly, persons with disabilities, or zero-bedroom dwelling unless a child of less than 6 years old resides in such housing)
  - There is <u>NOTHING</u> in writing instructing the inspector not to record peeling paint if the property is exempt (other than in places a child under 6 will not go) nor is there anything in writing that you will get your
- points back if it's recorded on an exempt property or unit without a child under 6.

  3. Tenant-owned personal property that are <u>NOT</u> considered components of the 3 inspectable areas: Unit, Inside, Outside (e.g., tenant-owned picture with broken glass would not be cited for sharp edges).

Certain tenant-owned items WILL be cited:

- 1. Any items affecting the performance of a fire safety system or puts the building at risk (e.g., tenants painting or blocking sprinkler heads)
- 2. Damaged/missing tenant-owned appliances where it is considered the primary item to meet affirmative requirements (e.g., tenant-owned refrigerator has a damaged seal)
- 3. Anything tenant-owned that violates affirmative requirements (e.g., unvented fuel-burning



### Key Takeaways: Final Rule – Administrative Procedures

- 1. Up to 5 additional units could be inspected if recommended by a resident council or tenant organization.
  - These 5 units will NOT be scored (unless one of them is already part of the NSPIRE sample)
  - Residents must submit unit recommendations through the automated system or email at least 30 days prior to the scheduled inspection. (HUD will allegedly inform residents when they can submit their recommendations approximately 180 days prior to inspection).
  - Even though not scored, all deficiencies must be corrected and evidence of correction for the 24-hour deficiencies must be communicated to HUD.
- 2. The inspection COULD INCLUDE VACANT UNITS REAC is seeking comment on this practice and will consider it for NSPIRE inspector protocols.
  - I highly recommend you email HUD at <a href="mailto:NSPIRERegulations@hud.gov">NSPIRERegulations@hud.gov</a> and convey your opinion on this.
- 3. PHAs and POAs are required to make inspection results available to residents.
- 4. HUD suggests notifying your residents at least 7 days in advance through multiple communication methods.

Constructive Forensics

### HUD PUBLISHES INSPECTION STANDARD FINAL NOTICE v3.0 HERE IS THE GOOD NEWS!

- 1. Under the Window Standard "Condensation that is present due to a failed window seal should not be evaluated"
- 2. Under Egress Standard (3rd floor and lower)
  - ✓ "Resident-owned property should NOT be evaluated as an obstruction to the rescue opening or to the fire escape access \*Don't get too excited - "A permanently installed window-mounted air conditioner" is still an obstruction
  - ✓ Only bedroom windows are considered Rescue Openings NOT living room windows (unless there is as fire escape)
- 3. Tenant-owned Fire Extinguishers and extinguishers not in service (in storage) will NOT be inspectable
- 4. A missing lightbulb from a fixture will NOT be recorded as an exposed Electrical Conductor, however the following still is: a. Hardwired smoke alarm with an exposed conductor

  - c. Wiring that is insulated but not protected by sheathing or conduit
  - d. Visible wire nuts on electrical conductors
  - Wall-mounted light fixture with a damaged or missing cover
  - Device cover plates missing/damaged
- GFCI/AFCI test or reset button missing
- h. NOW THE GAP MUST BE GREATER THAN ½ INCH!!!


### GOOD NEWS (Continued)

- 5. Under the new deficiency #5 for Electrical Conductor, Outlet and Switch: "Water is currently in contact with an electrical conductor," HUD clarified:
  - a. ONLY active leaks are to be cited (confirmed visually)
  - b. Leaks near a component confirmed to be waterproof would NOT be cited
- 6. Under the Sprinkler Assembly Standard
  - a. Paint or foreign material (like dust) must cover 75% or more of the sprinkler assembly or 75% or more of the glass bulb to be cited
  - b. Corrosion was added as a new deficiency
- 7. The Graffiti Standard has been REMOVED!
- 8. Handrails has a new deficiency #4 "No handrail is present and there is no evidence of previous installation."
  - a. Listed as N/A H&S Classification under Unit
  - b. The Final Rule states, "This deficiency will not be scored and there is no requirement for a correction,"
  - c. It IS listed as a "Low" H&S for Inside and Outside areas...thus will be scored (unless HUD manually turns off the scoring on their end somehow).
- 6. Under Mold-Like Substance Standard, the "Prescence of mold-like substances at very low levels" (under 4 sq inches) has been removed.
- NIS will not be a "designation" in NSPIRE... it has to be a poor repair on an inspectable item within NSPIRE. If paint is mismatched...paint (other than peeling paint on pre-1978 properties) is not a citable defect under NSPIRE.

### **Infestation Standard Issues** TITLE: INFESTATION VERSION: V3.0 DATE PUBLISHED: 06/20/23 DEFINITION: The presence of animals with potential impacts on resident health and safety. PURPOSE: None COMMON COMPONENTS: None LOCATION: $\boxtimes$ Kitchen, cabinet, refrigerator, cooking appliance, bathroom, furniture, bed, carpet, drapes (Note that Unit this is not an exhaustive list). $\boxtimes$ Kitchen, cabinet, refrigerator, cooking appliance, bathroom, furniture, carpet, drapes (Note that this Inside $\boxtimes$ Near refuse enclosure or anywhere garbage is present, eaves of roofing (Note that this is not an Outside exhaustive list).

### THE NOT SO GOOD NEWS

- 1. ALL Outside electrical outlets must be GFCI-protected (see Electrical GFCI or AFCI Outlet or Breaker Standard)
  - a. Remember this is an affirmative Standard not scored the first year
  - b. Don't forget...they have to meet code be weather resistant and have an in-use cover!
- Guardrails have been made a new Affirmative Habitability Requirement if the vertical distance measures more than 30 inches above the "floor or grade below."
  - a. Under More Information it states, "This deficiency should only be evaluated in areas that are accessible to the resident."
  - b. This could potentially be a costly impact on many properties without guardrails on their retaining walls, for example.
  - c. Local code exceptions could also possibly be honored.
- 3. Window screens have been specifically called out under Deficiency #4 of the Window Standards to be a Moderate H&S if they are damaged or missing (if there is evidence they were previously installed).
- 4. Structural System Standard deficiency, "Structural system exhibits signs of serious failure."
  - a. HUD states in the Rule that, "NSPIRE Inspectors will not be making structural stability assessments..."
  - b. Inspectors absolutely WILL be doing just that with this deficiency still in the standards!
- 5. Unbelievably, HUD will require that "permanent heating sources" be tested no matter what time of year it is.
- 6. The Infestation Standard is a complete and total disaster (next slide)



### Infestation Standard...the only good news

Page 15 in the NSPIRE Final Rule – Inspection Standards states the following:


"Within the correction timeframe, documentation must be provided for the pest management plan, and this documentation must include:

- 1. Start date of the plan
- 2. Servicing schedule
- 3. Methods of pest monitoring
- 4. Managing and treatment
- 5. And other factors as determined by HUD, the PHA and/or other relevant authority

Integrated Pest Management (IPM) is strongly encouraged – this uses prevention-based pest management methods with a focus on:

- 1. Identifying and correcting building conditions that contribute to infestation
- 2. Reducing use of pesticides (especially routine or untargeted pesticide application)
- 3. Modification of hygiene and sanitation practices in and on the property
- 4. Assessment and on-going monitoring to assure appropriate interventions as needed."

8



### Exceptions to the 3-2-1 Rule

- o Small Rural Public Housing Agencies (PHAs)
  - √ 550 or fewer combined public housing units and vouchers under section 8
    AND either of the following:
    - Has a primary administrative building with a physical address in a rural area, OR
    - More than 50% of its combined PH and Voucher units are in rural areas
- HUD will make the initial determination of PHAs that qualify as small rural no later than October 30, 2023 and every 3 years thereafter. You can also appeal HUD's decision.
- o Shall be assessed and scored based only on the physical condition of their public housing properties
- o Will be inspected no more than once every 3 years, unless designated as "troubled" which is defined as:
  - ✓ The weighted average score of all inspections is below 70% of the total available points, OR
  - ✓ Weighted average score between 70-80% of the total available points and has at least one property
    that receives fewer than 70% of the total available points
- o Troubled PHA properties, regardless of size, will be inspected annually based on fiscal year (FY) end

**416** 

### Failing Scores - Multifamily Housing Programs

**Multifamily Housing Programs** 

\*Refer to Housing Notice 2018-08

- 31 59: Issued a NOV and/or a NOD (Notice of Violation / Notice of Default)
  - 1. Conduct a 100% survey of the entire project
  - 2. Correct all deficiencies at the property, including those identified in the REAC inspection report and the owner's survey; and
  - 3. Submit to their Account Executive (AE) a copy of the owner's survey and a form certification that all deficiencies have been corrected.
- 0 30: Automatically referred to the DEC (Departmental Enforcement Center)
- 31 59 (2 years in a row) Discretionary referrals to the DEC.

HUD will take other review actions before referring to the DEC.

1

Constructive Forensics

ഒ



### Failing Scores - Public Housing

### PHA's

0 – 30: The DEC will evaluate the PHA's correction of LT and Severe deficiencies.
If the PHA is not responsive or does not correct these deficiencies, the PHA may be referred to the Assistant Secretary for Public and Indian Housing for sanctions or other actions.

31 – 59: PIH will retain some discretionary review of the PHA before or in place of a referral to the DEC.
This review will consider the PHA's rating under the Public Housing Assessment System (PHAS) and whether there are other administrative tools such as a Corrective Action Plan or PHAS Recovery Agreement that includes the property.

62

Constructive Forensics

### Appeals – per 2 Final Rules

Only 1 type of appeal now – Technical Review

The clock starts the day you receive your inspection report – you have 45 days!!!

- ✓ You must submit the appeal electronically in the online NSPIRE system
- ✓ Copy NSPIRERegulations@hud.gov
- ✓ And send a courtesy copy to your HUD field office representative

Reasons you can appeal:

- 1. HUD or inspector error
- 2. Adverse conditions beyond your control
- 3. Modernization work in progress
- 4. Conflicts with state or local code.



### Appeals – per 2 Final Rules (con't)

HUD will only accept and process appeals that have the potential to either:

- Increase your score from a fail to above a 60
- Increase your score so that it changes your inspection frequency

The evidence provided in the appeal must be objectively verifiable such as:

- ✓ Photographic evidence
- ✓ Written material from an objective source with subject matter expertise that pertains
  to the item being reviewed.
- Protocol from the NSPIRE Standard states to not cite the deficiency or to cite it in a different way.

Appeals will not be accepted for conditions that were repaired <u>AFTER</u> the inspection.

6

### Appeals – per 2 Final Rules (con't)

### Material Errors

- 1. Building data error
  - The inspector inspected the wrong building
  - The inspector inspected a building that was not owned by the property (including common or site areas)
  - Incorrect data to the failure of an owner or PHA to ensure HUD's systems of records are updated CANNOT be appealed.
  - Address and/or building names will not be considered as a material error.
- 2. Unit count error
  - This error occurs if the total number of units considered in scoring is incorrect due to the fault of HUD.
- 3. Non-Existent deficiency error
  - If the inspection records and observed deficiency that does not satisfy or does not meet a reasonable interpretation of the definition of that deficiency as defined by inspection procedures.

### Appeals – per 2 Final Rules (con't)

- 4. Adjustments for factors not reflected or inappropriately reflected in the physical condition score.
  - HUD might review the property's results if facts and circumstances affecting the property are not reflected or are reflected inappropriately in the inspection.
  - Inconsistencies between local code requirements and the HUD physical inspection protocol
  - Conditions that are permitted by local variance or license
  - Preexisting physical features that do not conform to, or are inconsistent with, HUD's physical condition protocol.
  - The project being scored for elements that it does not own and is not responsible for maintaining.

Adverse conditions beyond the control of the owner of PHA

- Damage caused by third parties such as a private entity or public entity undertaking work near the property resulting in damage.
- Natural disasters

66

### Appeals – per 2 Final Rules (con't)

Modernization work in progress

- Only the units that are currently undergoing modernization will have their scores adjusted!
- \*\*Make this a non-issue! Request an inspection extension and send to your local HUD office the following:
  - 1. Scope of work (including the start/end dates)
  - 2. Substantial rehab is \$18,392/unit

Total Cost of Rehab ÷ Number of Units = Total Cost Per Unit

3. Get the approval for the extension BEFORE the inspector contacts you!

What can happen as a result of a successful appeal?

- o A new inspection will be ordered (this will only occur if there are significant anomalies/errors)
- Correction of the original inspection
- o Issue a new physical inspection score

6

### Appeals – per 2 Final Rules (last slide)

When will HUD notify the property of the final decision?

- Within 90 days
- o Up to 120 days for the first year of NSPIRE implementation

PHAs or POAs that do not hear from REAC on the status of their appeal within 120 days

will have all the points relating to appealed deficiencies restored!




### Fire Safety NSPIRE "improves" fire safety standards in several ways from UPCS Implementation of National Fire Protection Association (NFPA) 72 (Smoke Alarms/Detectors) Minimum temperature requirement (68°) Permanent heating source requirement More stringent & specific fire door requirements


STANDARDS


Carbon Monoxide Alarm Smoke Alarm Trash Chute Sprinkler Assembly Exit Sign Fire Escape


Prohibition of fuel-burning unvented space heaters

Egress Fire Extinguisher Flammable & Combustible Item Clothes Dryer Exhaust Ventilation Door – Fire Labeled
























DEFICIENCY 1: LOCATION:	Sprinkler Assembly Standard  Sprinkler head assembly is encased or obstructed by an item or object that is within 18 inches of the sprinkler head.  ☑ Unit ☑ Inside ☑ Outside	LT H&S – 24 hours
More Information:	- Some sprinkler heads may not have 18" clearance due to features within the built environment (e.g., closet, wall mounted kirchen cabinets, permanently installed light fixture, exit sign) and should not be considered a deficiency under this Standard.  - Determine if items have been stored or stacked around the sprinkler head or if alterations have been made that impede the sprinkler head assembly.  - A parked vehicle within 18" of the sprinkler assembly should not be considered a deficiency under this Standard.  - Examples of encasements may include, but are not limited to:  - Painter's tape  - Plastic bag  - Examples of obstructions may include, but are not limited to:  - Furniture	1.0
89	- Shelves - Stacked materials	


		Spri	nkler Assembly Standa	ard	
DEFICIENCY 2:	Sprinkler assemb	ly component is damaged	, inoperable, or missing and it is detri	imental to performance.	
LOCATION:	<b></b> Unit		Outside		LT H&S – 24 hours
More Information:	ability to prop - Examples of c - Physical - Glass bu - Conceale	erly or adequately disch onditions that may be do damage alb has lost fluid	s caulked or glued to ceiling	V 10 10 10 10	mbly's
		No.			
90					


	Sprinkler Assembly Standard	e a caractería
DEFICIENCY 3: LOCATION:	Sprinkler assembly has evidence of corrosion.       ☑ Unit     ☑ Inside     ☑ Outside	LT H&S – 24 hours
INSPECTION PROCESS:  OBSERVATION:  REQUEST FOR HELP:  ACTION:  More Information:	<ul> <li>Look at the sprinkler assembly and its components to identify any evidence of corrosion.</li> <li>None</li> <li>None</li> </ul>	ZERO GUIDANCE!
malfunctioning sprin	deficiency is the <u>most important</u> of all 4 sprinkler assembly deficiencies be kler heads are cause by some kind of corrosion. CORROSION ANYWHERE ON THE SPRINKLER HEAD ASSEMBLY (including e	


	Sprinkler Assembly Standard
DEFICIENCY 4: LOCATION:	Sprinkler assembly has evidence of foreign material that is detrimental to performance.  ☑ Unit ☑ Inside ☑ Outside  LT H&S — 24 hours
ACTION:	- If foreign material is present, determine if it covers 75% or more of the sprinkler assembly or 75% or more of the glass bulb.
More Information:	<ul> <li>For the purpose of this Standard, a condition is detrimental to performance if it impacts the sprinkler assembly's ability to properly or adequately discharge when activated.</li> <li>Examples of foreign material that may be detrimental to performance may include, but are not limited to:         <ul> <li>Loading / dust</li> <li>Paint</li> </ul> </li> </ul>
93	


		Exit Sign Stan	dard	
DEFICIENCY 1: LOCATION:	Exit sign is damaged	I, missing, obstructed, or n	ot adequately illuminated.	LT H&S – 24 hours
- If present, visually insperis now not present or is		or evidence that indicates an e	xit sign was previously installed but	
			tteries may be remotely located.  the remote location and demonstr	ate
		es must be recorded as two	ndividual deficiencies, each within	its
		- Call		Str. Str.
94				


	Fire Escape Standard	
DEFICIENCY 1: LOCATION:	Fire escape component is damaged or missing.  Outside	LT H&S – 24 hours
DEFINITION:	An apparatus on the outside of a building used for escaping from a building on fire.	
MORE INFORMATION:	A blocked fire escape should be evaluated under the Egress standard.	
And The second s	door leading to the fire escape is blocked, refer to the Egress standard.	
- There is no requireme unit.	ent for inspectors to go on the fire escape as this is a visual observation from the ground or	
97		





























	Fire Extinguisher Standard	
DEFICIENCY 2: LOCATION:	Fire extinguisher service tag is missing, illegible, or expired.  ☐ Unit ☐ Inside ☐ Outside	LT H&S – 24 hours
DEFICIENCY CRITERIA:	The date on the service tag of any fire extinguisher has exceeded one year.  OR  The fire extinguisher tag is missing or illegible.	
	OR A nonchargeable or disposable fire extinguisher is more than 12 years old (based on manufacture date).  The POA provides the invoice or report from the servicing fire extinguisher company, do not record a deficiency for issing tag. The date of the report must be no more than one year from the inspection date.	
111		










DEFICIENCY 1:	Electri	dryer trans	ition du	uct is det	ached or	missing.					
LOCATION:	$\boxtimes$ (	nit 24	Σ	Inside							
DEFICIENCY 2:	Gas d	yer transitio	n duct i	is detache	ed or mis	sing.					
LOCATION:	$\boxtimes$ (	nit 24		Inside							
-9.775	10										
- If unable to locate the d	dryer transition	luct look habind	the cloth	an dame and	Laborate State		en deline of				
						nere is an ac	cumulation of				
dryer lint, which indicate						nere is an ac	cumulation of				
						nere is all ac	cumulation of				
	tes that the drye					ilere is all ac	cumulation of				
dryer lint, which indicate	Only:  Only:	transition duct	may be do	etached or n	nissing. hed and eval	uated under t	his deficiency.				
dryer lint, which indicate	Only:  Only:	transition duct	may be do	etached or n	nissing. hed and eval	uated under t	his deficiency.				
dryer lint, which indicate	Only:  Only:	transition duct	may be do	etached or n	nissing. hed and eval	uated under t	his deficiency.				
dryer lint, which indicate	Only:  Only:	transition duct	may be do	etached or n	nissing. hed and eval	uated under t	his deficiency.				
dryer lint, which indicate	Only:  Only:	transition duct	may be de	etached or n	nissing. hed and eval	uated under t	his deficiency.				















				Fire Doors (con't)	10.00	
		DEFICIENCY 1:	Fire labeled doo	or does not open.		
		LOCATION:	<b>☑</b> Unit	✓ Inside	24	
	1	DEFICIENCY 2:	Fire labeled doo close and latch.	or does not close and latch or the self-closing hardware is damaged or missing such that the door d		
	V.	LOCATION:	<b>☑</b> Unit		24	
		DEFICIENCY 3:	Fire labeled doo	or assembly has a hole of any size or is damaged such that its integrity may be compromised.	$\sim$	
		MORE INFORMATION:	Unit	✓ Inside	24	
	Wh	DEFICIENCY 4:	Fire labeled doo	or seal or gasket is damaged or missing.		
	NEW	LOCATION:	Unit		<b>24</b>	
		DEFICIENCY 5:	An object is pres	sent that may prevent the fire labeled door from closing and latching or self-closing and latching.		
	NEW	LOCATION:	<b>☑</b> Unit	Inside	24	
	300	DEFICIENCY 6:	Fire labeled doo	or cannot be secured.	$\sim$	
	NEW	LOCATION:	<b>⊠</b> Unit		24	
		DEFICIENCY 7:	Fire labeled doo	or is missing.	C .	
122	<b>V</b>	LOCATION:	<b>☑</b> Unit		24	B





DEFICIENCY 3 — UNIT:	FIRE LABELED DOOR ASSEMBLY HAS A HOLE OF ANY SIZE OR IS DAMAGED SUCH THAT ITS INTEGRITY MAY BE COMPROMISED.
DEFICIENCY CRITERIA:	A fire labeled door assembly has a hole of any size.
	OR
	A fire labeled door assembly is damaged (i.e., visibly defective; impacts functionality) such that its integrity may be compromised.
DEFICIENCY 3 — INSIDE:	FIRE LABELED DOOR ASSEMBLY HAS A HOLE OF ANY SIZE OR IS DAMAGED SUCH THAT ITS INTEGRITY MAY BE COMPROMISED.
DEFICIENCY CRITERIA:	A fire labeled door assembly has a hole of any size.
	OR
	A fire labeled door assembly is damaged (i.e., visibly defective; impacts functionality) such that its integrity may be compromised.
	OR
	25% of the door surface has rust that affects the integrity of the door.
	OR
	There is broken or missing glass.




















































AFCI/GFCI Code Requirements								
Updating receptacles to current code (in this case, installing GFCl's) is only required with new construction, alterations, modifications, repairs – typically, if you pull a permit, you will have to conform to the current code requirements but in the case of electric repairs/replacements you must upgrade per NEC 406.4.								
ALWAYS CHECK	VITH YOUR AHJ (Authority Having Jurisdiction) for their requirements!							
This rule is lis	ed as an Affirmative Habitability Requirement – HUD							
states in the Sta	ndards final rule pg 20 as well as the Risk Analysis that							
although	expensive, they are essential to resident safety.							
A LANGE								
NYCHA HQS RULE Kitche Bathro								
149								

	E	lectrical – GF	Cl or AFCl Ou	tlet or Breaker	– Def #1 ar	nd #2		
DEFICIENCY 1:			damaged and the test or re	eset button is inoperable.				
LOCATION:	<b>⊠</b> Unit		Outside		5	evere H&S	5 – 24 hours	
DEFICIENCY 2:	AFCI outlet or	AFCI breaker is not visibly	damaged and the test or	reset button is inoperable.				
LOCATION:	<b>⊠</b> Unit		Outside					
				_/-717	and the last			
	REQUEST FOR HELP:	device, television) on - If a personal item (e.	the same circuit as the GFCI	ted and may impact electrical outlet or GFCI breaker being plant, toy) is concealing the the item.	tested.	WOOD CONTRACTOR		
	More Information:	- An acceptable industr	d in series and may have on y standard tester may be us itandard 1436 for Outlet Circ	e GFCI that provides protection ed in place of the test and res cuit Testers.	to the entire series. set buttons if it meets	all requirements		
150								


	Electrical – GFCI or AFCI Outlet or Breaker – Def #3	
DEFICIENCY 3: LOCATION:	An unprotected outlet is present within six feet of a water source.  Unit — Affirmative Habitability Requirement  Outside — Affirmative Habitability Requirement	Severe H&S – 24 hours
DEFICIENCY CRITERIA:	Oudet is present within six feet of a water source (i.e., sink, bathtub, shower, water faucet, toilet) that is located in the same room.  AND  Oudet is not GFCI protected.	
ACTION:	<ul> <li>Once identified, measure from the center of each water source (i.e., sink, bathtub, shower, water faucet, toilet) to the center of each outlet located within the same room.</li> </ul>	
	(8) Sinks — where receptacles are installed within 1.8 m (6 ft) from the top inside edge of the bowl of the sink (9) Boathouses (10) Bathtubs or shower stalls — where receptacles are installed within 1.8 m (6 ft) of the outside edge of the bathtub or shower stall	2023 NEC / NFPA 70 210.8
151	For the purposes of this section, the distance from recepta- cles shall be measured as the shortest path the power supply cord connected to the receptacle would follow without piercing a floor, wall, ceiling, or fixed barrier.	




	Electrical – GFCI or AFCI Outlet or Breaker – Def #3
Good News:	
More Information:	- An outlet designated for a major appliance (e.g., water heater, HYAC, refrigerator, washing machine, dishwasher, garbage disposal, microwave, etc.) should not be evaluated under this standard, regardless of its distance from the water source.  - An outlet located below a countertop and within an enclosed cabinet should not be evaluated under this standard, regardless of its distance from the water source.
	- A dedicated outlet is a receptacle outlet that is only capable of serving that specific appliance.
Bad News:	
	ith older housing stock, this could be a pretty substantial financial burden to comply with. red a Severe H&S - a 24-hour repair

	Electrical – Service Panel Standard – Def #1
DEFICIENCY 1: LOCATION:	: Electrical service panel is not readily accessible.  ☑ Unit ☑ Inside ☑ Outside
DEFICIENCY CRITE	RM: Electrical service panel is not reasonably accessible (i.e., cannot be reached and opened without moving obstructions, dismantling, destructive measures, or actions that may pose a risk to persons or property).
	REQUEST FOR HELP:  - If a personal item (e.g., picture, calendar, rolling cart, dothing, small appliance, plant, toy) is concealing the electrical service panel and can reasonably be removed, ask the resident to move the item.
ia. I	More Information:  - If the electrical service panel servicing the Unit is located behind a locked door, and the resident or POA cannot unlock the door at the time of the inspection, then it is not reasonably accessible as defined by this standard.  - If the resident or POA cannot unlock the electrical service panel door at the time of the inspection, then it is not reasonably accessible as defined by this standard.
Electric	cked Electrical Equipment Rooms or Enclosures  cal equipment rooms or enclosures housing electrical apparatus that are liled by a lock(s) shall be considered accessible to qualified persons.







### How Do I Prepare for an NSPIRE Inspection? 1. Inspect the Units...as much as possible...and follow up that the repairs were completed HUD states in the NSPIRE Final Rule the following: "HUD agrees that owners and agents must abide by their rights and responsibilities which includes enforcing lease provisions and house rules and PHA policies alongside of their responsibilities to maintain the physical condition of the property, PHAs and owners can ensure that residents are aware of policies, understand their responsibilities, and collect reasonable fees for damages. PHAs and owners can also stay abreast of property conditions with regular inspections and the annual self-inspection process included in NSPIRE. HUD also agrees that additional punitive financial charges above what is allowed in the lease provisions and security deposit administration would likely not be an effective means to discourage tenant-induced damage." 2. EDUCATE the residents! The more they understand – the better off both of you will be. 3. Offer a small incentive to the residents like a Starbucks gift card or get a donation from a local business if they communicate with you. Ultimately you need to get the resident INVOLVED in the process because you can only "police" them so much! 4. You will have to upload ALL the information UPCS inspectors used to ask for (certificates, construction years, property profiles, unit occupancy, etc.) \*Don't forget LBP Exemption, if applicable!!!\* · PHAs must update IMS/PIC • REAC will allegedly contact you or the assigned field office 30 to 90 days prior to the planned inspection.



### **HUD ASSIST**

Powered By Constructive Forensics

- **Pre-REAC Inspections**
- Training and Education
- Appeal Consulting

**Get REAC-Ready.** 

Schedule your Pre-REAC Inspection today.

www.c4n6.com | HUDAssist@c4n6.com